

Maximum operating pressure:	0.86Mpa
Recommend pressure:	0.35-0.55Mpa
Max.hot water temperature:	80°C
Recommend hot water temperature:	49-72°C

## Recommended Tools for Installation:

Screwdriver	Hex Key	pencil	Drill
$\bigcirc$	Carrow	67	
Tape measure (3m-5m)	Drill bit (ø6. 5)		
Replacement Parts: 1.Thermostatic faucet 2. Decoration Cover 3. Rubber Washer 4. Brass Joints 5. Hexagon socket scru- 6. Shower Tube 7. Hand shower holder 8. Fixing Part 9. Fixing Part Cover 10. Self-tapping Screw 11. Plastic Screw 12. Fixing Base 13. Head shower 14. Filter Washer 15. Shower Hose 16.Hand Shower	1PC 2PCS 2PCS 2PCS 2PCS 2PCS 1PC		

1

